AD-A073 007

PRINCETON UNIV N J DEPT OF CHEMICAL ENGINEERING
A GENERALIZED TIME-TEMPERATURE-TRANSFORMATION PHASE DIAGRAM FOR-ETC(U)
SEP 79 J K GILLHAM
TR-18

I OF |
A073 007

I DEPT OF CHEMICAL ENGINEERING
N00014-76-C-0200
N00014-76-C-0200
NL

I OF |
A073 007


I DEPT OF CHEMICAL ENGINEERING
F/G 7/4
A GENERALIZED TIME-TEMPERATURE-TRANSFORMATION PHASE DIAGRAM FOR-ETC(U)
N00014-76-C-0200
NL

I OF |
A073 007

I DEPT OF CHEMICAL ENGINEERING
F/G 7/4
A GENERALIZED TIME-TEMPERATURE-TRANSFORMATION PHASE DIAGRAM FOR-ETC(U)
ND0014-76-C-0200
NL

I OF |
A073 007

A075 007







OFFICE OF NAVAL RESEARCH

Contract N00014-76-C-0200

Task No. NR 356-504

TECHNICAL REPORT NO. 18

A Generalized Time-Temperature-Transformation

Phase Diagram for Thermosetting Systems

by

J. K. Gillham

To be published in POLYMER



Polymer Materials Program

Department of Chemical Engineering

Princeton University


Princeton, NJ 08544

September 1979

Reproduction in whole or in part is permitted for any purpose of the United States Government

This document has been approved for public release and sale; its distribution is unlimited

J. K. Gillham Principal Investigator 609/452-4694



# A GENERALIZED TIME-TEMPERATURE-TRANSFORMATION PHASE DIAGRAM FOR THERMOSETTING SYSTEMS

John K. Gillham

Polymer Materials Program
Pepartment of Chemical Engineering
Princeton University
Princeton, NJ 08544

#### ABSTRACT

A generalized time-temperature-transformation diagram for the thermosetting process is presented in which the four physical states encountered (i.e., liquid, rubber, ungelled glass and gelled glass) are related to the time and temperature of cure.

Gelation and vitrification, as a consequence of quenching morphological development and chemical conversion respectively, are discussed with respect to control of material properties.

1	
Accession For	1
DDC TAB	1
Unamnounced Justification	1
By	4
Distribution Codes Aveilability Codes	-1
Avair	
Dist Spec	

#### GELATION AND VITRIFICATION

Gelation and vitrification are two macroscopic phenomena which are encountered as a consequence of the reactions which convert a liquid to a solid in the thermosetting process. On the molecular level, gelation corresponds to the incipient formation of branched molecules of mathematically infinite molecular weight and occurs at a critical and calculable extent of reaction for the particular reactive system (1). A network develops by intramolecular reactions of branched molecules. Eventually the total mass can be one molecule. Macroscopically, gelation is associated with a dramatic increase in viscosity and a corresponding decrease in processibility. Gelation times are usually measured rheologically by the time between the beginning of the reaction and the attainment of a fixed viscosity.

Vitrification is the formation of a glassy solid. In thermosets this usually follows gelation and then occurs as a consequence of the network becoming tighter through further chemical reaction (crosslinking). A network structure will be a rubber (elastomer) at a given temperature if the segments between junction points of the network are flexible. If the segments are immobilized by further chemical reaction, or by cooling, the structure will change to a glassy (vitrified) state. Vitrification can retard further reaction. The overall transformation from liquid to gel to rubber to glass due to chemical reaction is termed "cure".

The second secon

The properties of thermoset materials are intimately related to their formation (cure). The material properties therefore depend on the interplay between such factors as chemical reactants, viscosity chemical conversion, prior to gelation, gelation, phase separation, vitrification, time-temperature paths of cure, and limits of thermal stability. The following section discusses a generalized time-temperature-transformation diagram (Figure 1) which is instructive for understanding these interrelationships. It displays the four distinct material states which are encountered during cure; these are liquid, elastomer (rubber), ungelled glass and gelled glass.

The phase diagram may be constructed by measuring the time to gelation and the time to vitrification versus the isothermal temperature of cure (T<sub>cure</sub>). A convenient technique involves using a torsion pendulum in which the specimen is an inert substrate (generally glass braid) impregnated with the system under investigation (2). Use of a supported sample permits investigation of the complete cure process versus time, and after cure the thermomechanical behavior with the same specimen. Times to gelation and to vitrification are measured by the lapsed time to the maxima of mechanical loss peaks: transition temperatures are similarly located with respect to temperature.

A GENERALIZED PHASE DIAGRAM FOR THERMOSETTING SYSTEMS (Figure 1)

Consideration of the cure of a liquid thermosetting system at a series of constant temperatures leads to the conclusion that there will be three types of behavior depending on the temperature of cure (3).

At elevated isothermal temperatures, above the maximum glass transition temperature of the cured system  $(T_{gw})$  but in the absence of degradation, a curing liquid gels and forms an elastomer (rubber) but does not vitrify.

At low temperatures, above the glass transition temperature of the reactants  $\binom{T}{Resin}$  but below a critical temperature  $\binom{T}{gel}$ , the now viscous curing liquid can vitrify simply by an increase of molecular weight. If chemical reactions are quenched by vitrification it need not gel.

At intermediate temperatures  $(gel^T_g < T_{cure} < T_{g\infty})$ , the curing liquid first gels and later vitrifies.  $gel^T_g$  is the isothermal temperature at which gelation and vitrification occur at the same time.

The time to gelation is expected to decrease exponentially with increasing temperature since the chemical conversion at gelation is constant according to Flory's gelation theory. Activation energies for the reactions leading to gelation can therefore be obtained from plots of the logarithm of the time to gelation versus reciprocal temperature in degrees Kelvin (3,4). The time to vitrify passes through a minimum between  $\gcd^T_g$  and  $\operatorname{T}_{g^\infty}$  (4). This reflects the competition between the increased rate constants for reaction and the increasing chemical conversion required for vitrification at higher temperatures.

It is apparent that if reactions are quenched by the process of vitrification ( $T_{\rm cure} < T_{\rm gw}$ ), the glass transition temperature ( $T_{\rm g}$ ) of the system after isothermal cure will then equal the temperature of cure. The vitrification curve then provides the minimum time to reach the glass transition temperature which the reactive system can attain

at temperature T cure. It also follows that gel<sup>T</sup>g is the glass transition temperature of the reactive system at its point of gelation (3).

The cure/phase diagram therefore shows that the thermosetting process is usefully characterized by the three temperatures  $\operatorname{Resin}^T g'$  gel $^T g$  and  $^T g^{\omega}$ , which will vary from system to system.

The temperature between gel<sup>T</sup>g and T<sub>g®</sub> at which the time to vitrify is a minimum may be of practical importance beyond being the most economical temperature for producing solid from fluid. As a consequence of the exothermic reactions, cure of specimens below this temperature will lead to the inside vitrifying before the outside; and vice versa. The volumetric shrinkage on vitrification will result in a skin-core structure for the latter case with built-in curing stresses. (This type of structure with residual thermal stresses also results on cooling after cure since the outside cools more rapidly than the inside.)

Whereas Resin g' gel g and T are singular physical transition temperatures definable by a temperature (and time scale), thermal degradation cannot be so easily defined. Thermal degradation can lead to a gelled glass (as in Fig. 1); however other types of degradation can lead to other physical states (e.g. ungelled glass, liquid and gas).

The cure/phase diagram explains a number of practices in the field of thermosets.

If the storage temperature is below gel<sup>T</sup>g a reactive fluid material will convert to a vitrified solid of low molecular weight which is stable and can be later liquified by heat and processed; above gel<sup>T</sup>g the stored material will have a finite shelf-life for subsequent processing since gelation will occur before vitrification. (A gelled material does not flow in the usual sense.) This concept lies at the basis of a widespread technology which includes thermosetting molding compounds and "prepregs" with latent reactivity.

In general, if  $T_{cure} < T_{gw}$ , a reactive material will vitrify and full chemical conversion will be prevented; the material will then usually need to be

postcured above  $T_{g^{\infty}}$  for development of optimum properties. For the manufacture of objects of finite size it is necessary to go through a multi-step process because of the exothermic nature of the reactions. A more sophisticated approach for controlling highly exothermic systems is to cure the material by raising the temperature at a rate such that  $T_g$  and  $T_{cure}$  coincide.

For highly crosslinkable or rigid-chain polymeric materials  $T_{g^{\infty}}$  can be above the limits of thermal stability in which case the thermoset material may not have a measurable glass transition temperature and full chemical conversion of the original network-forming reactions would not be attained. For composite materials in which a component other than the cured resin is thermally sensitive,  $T_{g^{\infty}}$  for the thermosetting resin should be below temperatures which would lead to damage of any part of the assembly. (An example would be adhesive bonding of aluminum by a thermally stable epoxy.). Similarly, if a composite system cannot be heated above a limiting temperature because of its size, then the curing system should have its  $T_{g^{\infty}}$  below that limiting temperature. (An example would be painting an airplane in a hanger.)

It should be feasible to molecularly design systems such that  $T_g$  is above the temperature of cure. Suggestions include cure by small molecules which are able to diffuse through the glassy state, incorporation of sterically well situated reactive groups in the polymerizing system, and employment of systems with prominent glassy state relaxations (5).

The extent of cure affects not only the value of the glass transition but also properties at temperatures well below it. For example, it appears that the modulus at room temperature can be decreased and the intensity of the T < T relaxations (as measured by the area under the loss peaks) can be increased by post-cure (6,7). This suggests that the free volume is increased and that the density at RT is decreased by the post-cure in spite of the increase of T .

This is presumably a result of the glassy state being further from equilibrium at RT the higher the  $T_g$ . Subsequent physical aging at room temperature leads to densification and embrittlement as the material spontaneously relaxes.

If  $T_{g^\infty}$  is below room temperature, the polymer system will be used as an elastomer.

The cure/phase diagram is being extended to two-phase systems.

(Rubber is often incorporated in inherently brittle polymeric materials as a method for increasing toughness. The curing of rubber-modified systems often involves change from an initially homogeneous solution to a heterogeneous multiphase morphology.) Evidence has been presented to show that the process of gelation arrests the development of morphology, and therefore that the time to gelation can be used to control material properties (8). The gelation time can be varied by catalysts and temperature. Similarly, by reaction at different temperatures, a single chemical composition can produce distinctly different morphologies which in turn are responsible for distinctly different macroscopic behavior. The temperature of gelation, T<sub>gelation</sub>, is therefore a characteristic one for defining the morphology developed isothermally by a particular system (9).

Rubber particles nucleate and grow during the polymerization process. In general, as in crystallization, nucleation is favored by low temperatures whereas growth is favored by high temperatures. The

overall extent of phase separation can therefore be expected to be at a maximum at intermediate temperatures (9).

Quenching of the development of morphological changes by the phenomenon of gelation may be explained by an abrupt decrease in diffusion of rubbery material to the growing domains of rubber which occurs in the transformation from a viscous liquid to a soft gel as infinite molecules form in the process of gelation. This is a longer range and larger scale diffusion process than that which is involved in the quenching of chemical reactions which occurs in the transformation from a rubbery state to a glassy state (vitrification) by restrictions on the more localized motions of chemically reactive parts of the molecules.

The cure/phase diagram is idealized in several respects.

If there are competing network-forming reactions having different reaction rates then different time-temperature paths will lead to different molecular networks in the fully cured materials and so to different material behavior.  $T_{g^{\infty}}$  and  $gel^Tg$  will vary accordingly. For example, values for  $T_{g^{\infty}}$  may be higher after prolonged initial reaction at low rather than at high temperatures prior to completion of the reactions by post-cure (7).

Vitrification times will be longer than those measured operationally from the time to the peak of the mechanical loss maximum assigned to the vitrification process since vitrification, with respect to the quenching of reactions, is better defined when the rigidity levels off (6).

The macroscopic assignment of gelation by a rheological measurement (which corresponds to an isoviscosity measurement) does not necessarily correspond to its molecular definition (which corresponds to an isocompositional state). However, values obtained rheologically for the activation energies of reactions leading to gelation can be close to those determined from times to reach constant chemical conversion (6,10,11).

The phase-diagram (above) has been obtained experimentally from a series of isothermal reactions. A similar diagram can be obtained for a given system from a series of temperature-programmed scans from low to high temperature at different heating rates (7). A typical scan will then reveal glassy-state relaxations of the unreacted resin below its glass transition,  $Resin^Tg$ , gelation, vitrification, devitrification (i.e. Tg), and above Tgmometric Tg re-vitrification due to degradation.

#### CONCLUSION

Experimental examination of the phenomena encountered in the thermosetting process has led to a generalized time-temperature-transformation phase diagram which provides a theoretical and convenient basis for understanding the factors which bear on the molecular engineering of thermosetting materials.

#### REFERENCES

- 1. P. J. Flory, "Principles of Polymer Chemistry", Cornell University Press, Ithaca, New York (1953).
- 2. J. K. Gillham, A.I.Ch.E. Journal 20, 1066 (1974).
- P. G. Babayevsky and J. K. Gillham, J. Appl. Polym. Sci., <u>17</u>, 2067 (1973).
- 4. J. K. Gillham, J. A. Benci, and A. Noshay, J. Polym. Sci., Symposium No. 46, 279 (1974).
- 5. M. B. Roller, Polym. Eng. Sci., 19, 692 (1979).
- 6. J. K. Gillham, Polym. Eng. Sci., 19, 676 (1979).
- A. F. Lewis, M. J. Doyle, and J. K. Gillham, Polym. Eng. Sci., 19, 661 (1979).
- 8. J. K. Gillham, C. A. Glandt, and C. A. McPherson, in "Chemistry and Properties of Crosslinked Polymers", p. 491, S. Labana, ed., . . . . . Academic Press, N.Y. (1977).
- L. T. Manzione and J. K. Gillham, Amer. Chem. Soc., Division of Organic Coatings and Plastics Chemistry, Preprints, 41, 364 (1979).
- M. B. Roller and J. K. Gillham, Amer. Chem. Soc., Symposium Series, No. 78, (Ed. R. C. Strand), 53 (1978).
- 11. N. S. Schneider, J. F. Sprouse and G. L. Hagnauer, Polym. Eng. Sci., 19, 304 (1979).

### ACKNOWLEDGMENT

Partial support has been provided by the Chemistry Branch of the Office of Naval Research.

#### FIGURE CAPTION

Figure 1. Time-temperature-transformation diagram:

time to gel and time to vitrify vs isothermal cure

temperature. Resin g gel g and

T are critical temperatures in the phase diagram

which shows the four states of materials encountered

in the thermosetting process, i.e., liquid, rubber,

ungelled glass, and gelled glass.

THE THERMOSETTING PROCESS

TIME-TEMPERATURE-TRANSFORMATION
PHASE DIAGRAM




Fig. 1

472:GAN:716:tam 78u472-608

## TECHNICAL REPORT DISTRIBUTION LIST, 356A

Agreens and Agreen	No. Copies	no i to a la constant de la constant	No. pies
Mr. Robert W. Jones Advanced Projects Manager Hughes Aircraft Company		Dr. T. J. Reinhart, Jr., Chief Composite and Fibrous Materials Branch Nonmetallic Materials Division	Def Dep
Mail Station D 132 Culver City, California 90230	<b>1</b>	Department of the Air Force Air Force Materials Laboratory (AFSC) Wright-Patterson Air Force Base, Ohio	4543
Dr. C. Giori		ANALYS SELECTION OF THE	
IIT Research Institute		Dr. J. Lando	
10 West 35 Street		Department of Macromolecular Science	9.0
Chicago, Illinois 60616	laved	Case Western Reserve University Cleveland, Ohio 44106	ank.
Dr. M. Litt		estaurs -	
Department of Macromolecular Science		Dr. J. White	
Case Western Reserve University Cleveland, Ohio 44106	1	Chemical and Metallurgical Engineering University of Tennessee	180
		Knoxville, Tennessee 37916	1
Dr. R. S. Roe		William State detailed and a service of	
Department of of Materials Science		Dr. J. A. Manson Materials Research Center	
and Metallurgical Engineering		Lehigh University	
University of Cincinnati Cincinnati, Ohio 45221	1	Bethlehem, Pennsylvania 18015	1
Dr. L. E. Smith		Dr. R. F. Helmreich	
U.S. Department of Commerce		Contract RD&E	
National Bureau of Standards		Dow Chemical Co.	
Stability and Standards		Midland, Michigan 48640	1
Washington, D.C. 20234	1	42 anh a 18 . V . v	m 1
was in the court of the court o		Dr. R. S. Porter	
Dr. Robert E. Cohen		University of Massachusetts	
Chemical Engineering Department		Department of Polymer Science and	
Massachusetts' Institute of Technolog	y	Engineering	
Cambridge, Massachusetts 02139	SA 1	Amherst, Massachusetts 01002	1
Dr. David Roylance		Professor Garth Wilkes	
Department of Materials Science and		Department of Chemical Engineering	
Engineering		Virginia Polytechnic Institute and	
Massachusetts Institute of Technolog	y	State University	
Cambridge, Massachusetts 02039	498	Blacksburg, Virginia 24061	1
Dr. T. P. Conlon, Jr., Code 3622		Dr. Kurt Baum	
Sandia Laboratories		Fluorochem Inc.	
Sandia Corporation		6233 North Irwindale Avenue	
Albuquerque, New Mexico	upd	Azuza, California 91702	1
Dr. Martin Kaufmann, Head		Professor C. S. Paik Sung'	
Materials Research Branch, Code 4542		Department of Materials Sciences and	
Naval Weapons Center .		Engineering	
China Lake, California 93555	. 1	Massachusetts institute of Technology	
	A STATE OF THE PARTY OF THE PAR	Combridge Massachusette 02139	1

472:GAN:716:Eam. 78u472-608

# TECHNICAL REPORT DISTRIBUTION LIST, 356A

Co	No. opies		No.
		No. (1998)	
Dr. Stephen H. Carr		Picatinny Arsenal	
Department of Materials Science		SMUPA-FR-M-D	
Northwestern University	120.00	Dover, New Jersey 07801	
Evenston, Illinois 60201	10 <b>1</b> 17	Attn: A. M. Anzalone Building 3401	1
Dr. M. Broadhurst		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Bulk Properties Section		Dr. J. K. Gillham	
National Bureau of Standards		Princeton Shiversity	
U.S. Department of Commerce		Department of Chemistry	
Washington, D.C. 20234	. 2	Princetok, New Jersey 08540	1
Dr. T. A. Litovitz		Douglas Aircraft Co.	
Department of Physics.		3855 Lakewood Boulevard	
Catholic University of America		Long Beach, California 90846	
Washington, D.C. 20017	1	Attn: Technical Library	
washington, b.c. 2001		C1 290/36-84	
Dr. R. V. Subramanian		AUTO-Sutton	1
Washington State University		Dr. E. Baer	
Department of Materials Science		Department of Macromolecular Science	
Pullman, Washington 99163		Case Western Reserve University	
3/061 steet Comman 2/2/20			1
Dr. M. Shen		Cleveland, Ohio 44106	
Department of Chemical Engineering		D. V D D.	
University of California		Dr. K. D. Pae	
Berkeley, California 94720	rod rod	Department of Mechanics and Materials Science	u.
Dr. V. Stannert		Rutgers University	
Department of Chemical Engineering		New Brunswick, New Jersey 08903	1
North Carolina State University			
Raleigh, North Carolina . 27607	1	NASA-Lewis Research Center	
(1) 10 10 10 10 10 10 10 10 10 10 10 10 10		21000 Brookpark Road	
Dr. D. R. Uhlmann		Cleveland, Ohio 44135	
Department of Metallurgy and Material Science		Attn: Dr. T. T. Serofini, MS-49-1	1
Center for Materials Science and		Dr. Charles H. Sherman, Code TD 121	
Engineering		Naval Underwater Systems Center	
Massachusetts Institute of Technology			1
Cambridge, Massachusetts 02139	3	antranslers	
Osabi 10ge, massecration of the contract of th		Dr. William Risen	
Naval Surface Weapons Center		Department of Chemistry	
White Oak		Brown University	
		Providence, Rhode Island 02192	1
		startence, whose salend Asias '	
Attn: Dr. J. M. Augl	•	De Alex Cont.	
Dr. B. Hartman		Dr. Alan Gent	
		Department of Physics	
Dr. G. Goodman		University of Akron	
Globe Union Incorporated		Akron, Ohio 44304	1
5757 North Green Bay Avenue			
Milwaukee, Wisconsin 53201	1		

13 SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered) READ INSTRUCTIONS
BEFORE COMPLETING FORM REPORT DOCUMENTATION PAGE RECIPIENT'S CATALOG NUMBER 1. REPORT NUMBER Technical Report No. 18 Technical Report 4. TITLE (and Subtitle) A Generalized Time-Temperature-Transformation Sep 33978-Sep 33979 Phase Diagram for Thermosetting Systems 6. PERFORMING ORG. REPORT NUMBER 7. AUTHOR(s) S. CONTRACT OR GRANT NUMBER(s) N00014-76-C-0200 J. K./Gillham 9. PERFORMING ORGANIZATION NAME AND ADDRESS 10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS Polymer Materials Program Department of Chemical Engineering/ Task No. NR 356-504 Princeton University, Princeton, NJ 08544 12. REPORT DATE 11. CONTROLLING OFFICE NAME AND ADDRESS (//) Sep Office of Naval Research NUMBER OF PAGES 800 North Quincy St. Arlington, VA 22217

14. MONITORING AGENCY NAME & ADDRESS(II different from Controlling Office) 15. SECURITY CLASS. (of this report) 15a. DECLASSIFICATION/DOWNGRADING 16. DISTRIBUTION STATEMENT (of this Report) Approved for Public Release; Distribution Unlimited 17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, If different from Report) 18. SUPPLEMENTARY NOTES 19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Thermosetting Systems Transitions Phases 10. ABSTRACT (Continue on reverse side if necessary and identify by block number) A generalized time-temperature-transformation diagram for the thermosetting process is presented in which the four physical states

encountered (i.e., liquid, rubber, ungelled glass and gelled glass) are related to the time and temperature of cure. Gelation and

vitrification, as a consequence of quenching morphological development and chemical conversion respectively, are discussed with respect to control

DD 1 JAN 73 1473 EDITION OF 1 NOV S IS OBSOLETE

of material properties.

401 377

472:GAN:716:tam 78u472-608

## TECHNICAL REPORT DISTRIBUTION LIST, GEN

fense Documentation Center ilding 5, Cameron Station exandria, Virginia 22314  S. Army Research Office D. Box 1211 search Triangle Park, N.C. 27709 tn: CRD-AA-IP  val Ocean Systems Center in Diego, California 92152 tn: Mr. Joe McCartney  val Weapons Center ina Lake, California 93555 tn: Dr. A. B. Amster Chemistry Division  val Civil Engineering Laboratory rt Hueneme, California 93401 tn: Dr. R. W. Drisko	1 1
ilding 5, Cameron Station exandria, Virginia 22314  S. Army Research Office D. Box 1211 search Triangle Park, N.C. 27709 tn: CRD-AA-IP  val Ocean Systems Center n Diego, California 92152 tn: Mr. Joe McCartney  val Weapons Center ina Lake, California 93555 tn: Dr. A. B. Amster Chemistry Division  val Civil Engineering Laboratory rt Hueneme, California 93401	1
Examdria, Virginia 22314  S. Army Research Office  D. Box 1211  Search Triangle Park, N.C. 27709  th: CRD-AA-IP  val Ocean Systems Center  n Diego, California 92152  th: Mr. Joe McCartney  val Weapons Center  ina Lake, California 93555  th: Dr. A. B. Amster  Chemistry Division  val Civil Engineering Laboratory  rt Hueneme, California 93401	1
S. Army Research Office D. Box 1211 search Triangle Park, N.C. 27709 th: CRD-AA-IP  val Ocean Systems Center n Diego, California 92152 th: Mr. Joe McCartney  val Weapons Center ina Lake, California 93555 th: Dr. A. B. Amster Chemistry Division  val Civil Engineering Laboratory rt Hueneme, California 93401	1
D. Box 1211 search Triangle Park, N.C. 27709 th: CRD-AA-IP  val Ocean Systems Center n Diego, California 92152 th: Mr. Joe McCartney  val Weapons Center ina Lake, California 93555 th: Dr. A. B. Amster Chemistry Division  val Civil Engineering Laboratory rt Hueneme, California 93401	1
D. Box 1211 search Triangle Park, N.C. 27709 th: CRD-AA-IP  val Ocean Systems Center n Diego, California 92152 th: Mr. Joe McCartney  val Weapons Center ina Lake, California 93555 th: Dr. A. B. Amster Chemistry Division  val Civil Engineering Laboratory rt Hueneme, California 93401	1
search Triangle Park, N.C. 27709 th: CRD-AA-IP  val Ocean Systems Center in Diego, California 92152 th: Mr. Joe McCartney  val Weapons Center ina Lake, California 93555 th: Dr. A. B. Amster Chemistry Division  val Civil Engineering Laboratory rt Hueneme, California 93401	1
val Ocean Systems Center in Diego, California 92152 tn: Mr. Joe McCartney  val Weapons Center ina Lake, California 93555 tn: Dr. A. B. Amster Chemistry Division  val Civil Engineering Laboratory rt Hueneme, California 93401	1
val Ocean Systems Center n Diego, California 92152 tn: Mr. Joe McCartney  val Weapons Center ina Lake, California 93555 tn: Dr. A. B. Amster Chemistry Division  val Civil Engineering Laboratory rt Hueneme, California 93401	1
n Diego, California 92152 th: Mr. Joe McCartney  val Weapons Center ina Lake, California 93555 th: Dr. A. B. Amster Chemistry Division  val Civil Engineering Laboratory rt Hueneme, California 93401	1
n Diego, California 92152 th: Mr. Joe McCartney  val Weapons Center ina Lake, California 93555 th: Dr. A. B. Amster Chemistry Division  val Civil Engineering Laboratory rt Hueneme, California 93401	1
tn: Mr. Joe McCartney  val Weapons Center  ina Lake, California 93555  tn: Dr. A. B. Amster  Chemistry Division  val Civil Engineering Laboratory  rt Hueneme, California 93401	1
val Weapons Center ina Lake, California 93555 tn: Dr. A. B. Amster Chemistry Division val Civil Engineering Laboratory rt Hueneme, California 93401	1
ina Lake, California 93555 th: Dr. A. B. Amster Chemistry Division val Civil Engineering Laboratory rt Hueneme, California 93401	
ina Lake, California 93555 th: Dr. A. B. Amster Chemistry Division val Civil Engineering Laboratory rt Hueneme, California 93401	
ina Lake, California 93555 th: Dr. A. B. Amster Chemistry Division val Civil Engineering Laboratory rt Hueneme, California 93401	
tn: Dr. A. B. Amster Chemistry Division val Civil Engineering Laboratory rt Hueneme, California 93401	
Chemistry Division val Civil Engineering Laboratory rt Hueneme, California 93401	
val Civil Engineering Laboratory rt Hueneme, California 93401	
rt Hueneme, California 93401	
rt Hueneme, California 93401	
th: Dr. K. W. Drisko	
	,
nterey, California 93940	1
. A. L. Slafkosky	
	1
entageon, see. 10500	
fine of Manual Passarch .	
tn: Dr. Richard S. Miller	1
napolis, Maryland 21401	
tn: Dr. G. Bosnajien	
Applied Chemistry Division	1
2 and the second bare manager	
val Ocean Systems Center	
	1
	ofessor K. E. Woehler partment of Physics & Chemistry val Postgraduate School nterey, California 93940  . A. L. Slafkosky ientific Advisor mmandant of the Marine Corps (Code RD-1) shington, D.C. 20380  fice of Maval Research 0 N. Quincy Street lington, Virginia 22217 tn: Dr. Richard S. Miller  val Ship Research and Development Center napolis, Maryland 21401 tn: Dr. G. Bosmajian